

LEGEND OF COMPONENTS

TP – THERMAL PROTECTION
AP2 K1 – OUTPUT BOARD POWER RELAY
AP2 K2 – MOTOR RELAY
AP2 K3 – HEAT RELAY
DASHED LINES = OPTIONAL (NOT ON ALL MODELS)

NOTE
POWER SUPPLY WIRING MUST HAVE CORRECT POLARITY AND GROUNDING FOR THE UNIT TO OPERATE CORRECTLY.

WARNING
Failure to install, maintain, and/or operate this machine according to manufacturer's instructions may result in conditions which can produce bodily injury and/or property damage.

REMARQUE
Le câblage d'alimentation électrique doit être correctement polarisé et mis à la terre pour que l'appareil fonctionne correctement.

AVERTISSEMENT
Si vous n'installez pas, n'effectuez pas les opérations d'entretien et/ou ne faites pas fonctionner cette machine conformemènt aux instructions du fabricant, vous favorisez les situations dangereuses tant au niveau des blessures corporelles quÀ celui des dommages a' la propriete' qui pourraient en resultér.

DRYER MARINE
3 PHASE ELECTRIC

SCHEMATIC	REV 00	515744



LEGEND OF COMPONENTS

TP – THERMAL PROTECTION
AP2 K1 – OUTPUT BOARD POWER RELAY
AP2 K2 – MOTOR RELAY
AP2 K3 – HEAT RELAY
DASHED LINES = OPTIONAL (NOT ON ALL MODELS)

DRYER MARINE 3 PHASE ELECTRIC		
CONNECTION	REV 00	515744